



Service Bulletin

File in Section: -

Bulletin No.: PIT5412

Date: May, 2015

PRELIMINARY INFORMATION

Subject: Headlamps Inoperative After Switching To Snow Plow Lights (GM Upfitter 116)

Models: 2014 Chevrolet Silverado 1500
2015 Chevrolet Silverado
2014 GMC Sierra 1500
2015 GMC Sierra

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some owners with snow plow equipment may notice when they switch from the factory (vehicle) headlights to the snow plow headlights, the snow plow headlights may be inoperative. When checking for DTC's, the BCM may have set a B2575 and/or B2699.

Recommendation/Instructions

Please reference the latest version of GM Upfitter Integration Bulletin 116 for additional information on these circuits. It can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.