



SI M12 04 15
Engine Electrical Systems

June 2015
Technical Service

This Service Information bulletin supersedes SI M12 04 15 **dated March 2015**.

NEW designates changes to this revision

SUBJECT

NEW **B38, B46, and B48 Engines: Engine Noise, Drivability Complaints, and Various DME Faults**

MODEL

F55 (Cooper, Cooper S)

F56 (Cooper, Cooper S, JCW)

With manual transmission

SITUATION

The vehicle exhibits one the following complaints:

- **NEW** Noise from the lower engine area, described as a high-pitched whine
- **NEW** Loss of power when idling
- **NEW** At a higher engine speed (above 3,000 rpm), a brief decrease in the engine speed can be felt.
- **NEW** Extended cranking before the engine will start
- **NEW** The customer notices an increased level of "free play" in the clutch pedal when changing gears.
- **NEW** The clutch pedal remains depressed, and will not return to the disengaged position.
- **NEW** Emergency operation is active, with one or more of the faults listed below.

Faults stored in the vehicle:

- 160020 Crankshaft sensor, signal: implausible
- 180001 Catalytic converter: efficiency too low
- 200D0C Powertrain, safety function: bus signal rpm reduction implausible
- 11A002 Fuel high pressure, plausibility: Pressure too low
- 1F054D Powertrain, safety function: powertrain reduced power, DSC-signal implausible
- 120408 Boost pressure control: Shut-down as a consecutive reaction

PROCEDURE

Submit an engine TeileClearing case with "B38, B46, and B48 Drivability Complaints" in the subject line, and wait for a response.

WARRANTY INFORMATION

Not applicable.

[Copyright ©2015 BMW of North America, Inc.]