



SB-10059180-1104

File in Section: -

Bulletin No.: PIC6039A

Date: April, 2015

Service Bulletin

PRELIMINARY INFORMATION

Subject: Informational Front And Rear Fuse Block Terminated Leads

Models: 2011-2015 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During normal diagnosis, you may notice that the main power feed going to the following fuse blocks may be damaged or have poor terminal retention.

A dealer technician may comment that they cannot locate the Terminals for the following fuse blocks to perform a service repair

1. X51L Left Instrument Fuse block
2. X51R Right Instrument Fuse block
3. X53 Rear Fuse block

Recommendation/Instructions

The Terminal is a rosebud terminated lead that is currently not available from SPO or the Warranty Parts Center (WPC) and the effected wiring harness will need to be replaced.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.