



Technical Service Bulletin

Subject:

Ramp Door Bolts On Momentum Toyhauler

Number

15-002

Date

8/21/2015

Model

Momentum

Build Date

All

Circulate To:

x

Service Manager

x

Parts Manager

x

Technician

x

Warranty Processor

Sales Manager

Concern:

Bolts used to secure the ramp door to the rear bumper may become loose over time

Remedy :

Remove existing bolt, drill 27/64 hole, install 1/2" self threading bolt pn 960989. Complete on all bolts that secure the door to the bumper

Flat Rate Code: Use flat rate code 560042, Time allowed for this repair is .7



If you have any further questions or need assistance please contact our technical service team at 574- 825-9679