



Parts Bulletin

TITLE:

**Seal Rear Tail Lamps Prior to Vehicle Sale
Model Year 2016 XC90**

GROUP: 35	CAT/NO: D39594	REFERENCE BULLETINS: QB:D39594, TJ: 30417	CAR MARKET: United States and Canada		
COPY TO / CIRCULATIONS (PLEASE INITIAL):				DATE:	
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	YEAR 2015	MONTH 11
				DAY 11	
					Page 1 of 1

“Right first time in Time”

UPDATE NOTES: Changed end date for action

Reference Bulletins: QB:D39594, TJ: 30417

IMMEDIATE VEHICLE UPGRADE PRIOR TO SALE REQUIRED

Volvo Cars of North America, LLC (Volvo) on behalf of Volvo Car Corporation has decided to launch a Quality Bulletin Delivery Action (D39594) for certain model year 2016 XC90 vehicles.

Volvo has identified that the sealing for the upper fixation pin on both tail lamps is not in the correct position. This condition may allow water to leak in the vehicle.

The corrective action is to seal both rear tail lamp upper fixation points per the attached TJ 30417.

Vehicles in retailer inventory must be upgraded prior to sale.

Please contact owners of any sold vehicles and schedule an appointment to have this repair performed.

PLEASE NOTE: QB-D action will be in effect until April 30, 2016 regardless of mileage.

The following part number applies:

Part Number	Description	Qty
30779431	Sealing	2