

---

## ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JUNE 2015

---

45151 2015 Transit Front Door and Fender Touch Condition

Some 2015 Transit vehicles may experience a touch condition between either front door and the fender resulting in possible paint or other body related damage. Engineering is aware of this issue that can be caused by either a gap alignment concern between the door and fender or an over extension of the door. If there is no other damage to the door and fender, verify the door and fender gap alignment is at 6mm and repair the paint damage. Monitor OASIS for further information.

---