

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JUNE 2015

45172 2015 3.7L And 5.0L Mustang- Exhaust Rattle, Knock Noise

Some 2015 Model Year Mustang vehicle built on or before 3/30/15, equipped with 3.7L Duratec 4V and 5.0L Ti-VCT V8 engines may exhibit exhaust rattle/knock noise emitting from the muffler resonator. Elevating idle to 1500 RPM and performing throttle tip-in, tip-out events in neutral will assist in confirming noise concern and is not to be confused with an exhaust leak that was addressed with a previously released TSB on 2015 Mustang 5.0L Ti-VCT V8 equipped vehicles. Updated muffler resonator assemblies are now available to resolve vehicle concern. Reference Workshop Manual Section 309-00B or 309-00C Exhaust System for component location and Removal and Installation procedure.