

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2015090006, October 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 218, Model Year 2015**
Update Transmission Control Module Software

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that on the subject vehicles, the transmission control module software does not correspond to the current series production configuration. An authorized Mercedes-Benz dealer will update the transmission control module software at the next workshop visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 115 vehicles are affected.

Order No. P-SC- 2015090006

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin






Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

Note:

- Use DAS/Xentry 09-10-11/15 with all associated patches or higher.
 - Follow the steps exactly as described in DAS/Xentry.
 - Connect battery charger (battery voltage  >12.5V).
 - Ensure all electrical consumers are switched-off.
 - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the "pre-call" check list before contacting UHD
 - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. Update fully integrated transmission control module (VGSNAG3) software:
Quick test view  VGS  Transmission control for 9-speed transmission (Y3/8n4) 
Adaptations  Control unit update  Update of control unit software.
 2. Follow on-screen instructions.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058).
Star Diagnosis System (SDS), Connect/disconnect (02-4762).
Update fully integrated transmission control module software (02-9304).

Damage Code	Operation Number	Labor Time (hrs.)
54 985 48 8	02-5058	0.1
	02-4762	0.1
	02-9304	0.1

Note

Operation Number labor times are subject to change.