



Service Bulletin

File in Section: -

Bulletin No.: PIP5292A

Date: September, 2015

PRELIMINARY INFORMATION

Subject: Clutch Chatter Without A Crankshaft End Play Concern

Models: 2014-2015 Chevrolet Corvette
Built with an 6.2L LT1 engine and manual transmission.

This PI was superseded to remove RPO codes for the transmission. Please discard PIP5292.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may have a concern of a clutch chatter when driving the vehicle

Recommendation/Instructions

If SI indicates the crankshaft end play is within specification, inspect for a missing crankshaft pilot bearing.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
8430570	Clutch Pilot Bearing Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.