



# Service Bulletin

File in Section: -

Bulletin No.: PIP5332

Date: October, 2015

## PRELIMINARY INFORMATION

**Subject:** Transmission oil in the TPIM at the AUX pump connector

**Models:** 2011-2015 Chevrolet Volt  
2014-2015 Cadillac ELR

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Transmission fluid found in the Power Inverter Module (PIM) aux pump connector.

### Recommendation/Instructions

Please replace the Aux pump with new harness and clean T6 Power Inverter Module (PIM) connections.

**Note:** During Drive unit repairs you may notice transmission fluid in the T6 Power Inverter Module (PIM). Do not replace the T6 PIM.

Tilt the T6 PIM so we came remove as much fluid from the PIM as possible and reinstall on vehicle

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

**Important:** Please reference the lasted version of PIP4840 when order the motor