

© 2015 Mazda Motor of America, Inc.


Subject: WHITE DOOR ARMREST(S) PINK DISCOLORATION	Bulletin No: 09-046/15
	Last Issued: 12/22/2015

APPLICABLE MODEL(S)/VINS

2014-2016 Mazda6 vehicles with VINs lower than JM1 GJ ***** 458701 (produced before November 09, 2015)

DESCRIPTION

Some customers may complain about a white door armrest(s) pink discoloration. The discolored armrest does not match the other white parts of the door panel.



Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace all 4 door panels. Refer to MS3 online or Workshop Manual section 09-17:
 - FRONT DOOR TRIM REMOVAL/INSTALLATION
 - REAR DOOR TRIM REMOVAL/INSTALLATION
3. Verify repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical—including photocopying and recording and the use of any kind of information storage and retrieval system—without permission in writing.

PART(S) INFORMATION

Part Number	Description	Qty.	Note
GMN5-68-420D-39 *	TRIM(R),DOOR	1	Replace all 4 door panels
GMN5-68-450D-39 *	TRIM(L),DOOR	1	
GMN6-68-420D-39 *	TRIM(R),DOOR	1	
GMN6-68-450D-39 *	TRIM(L),DOOR	1	
GMN5-68-520B-39 *	TRIM(R),DOOR-REAR	1	
GMN5-68-550B-39 *	TRIM(L),DOOR-REAR	1	

* Use GEPC with VIN to lookup part number.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.
- Replace all 4 door panels.

Warranty Type	A
Symptom Code	49
Damage Code	9X
Part Number Main Cause	**** 68 420, ****68 450, ****68 520, ****68 550
Quantity	1
Operation Number / Labor Hours:	XXL97XRX / 0.6 Hrs.