



GROUP
Electrical

MODEL
**2014~2015MY
Sorento (XMα)**

NUMBER
PS375

DATE
January 2015



TECHNICAL OPERATIONS

SUBJECT: SORENTO (XMα)- INTERMITTENT NO CRANK/START

On some 2014-2015MY Sorento (XM), customers may experience a concern related to an intermittent no crank/start, especially after an overnight cold soak. To address this concern, replace both Start 1 and Start 2 relays in the fuse box by referring to the appropriate Service Information on KGIS.

Part Number	Description
95230 2P030	Start 1 Relay
95230 2P050	Start 2 Relay

NOTE: This concern is not related to TSB ELE 069 and TSB ELE 057 / SA163A for vehicles equipped with PTG. Before replacing Start 1 and Start 2 relays, ensure that the battery is in good operating condition to rule out the possibility of no crank/start due to intermittent parasitic draw.

