

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013-2015MY BRZ
2006-2007MY B9 Tribeca

NUMBER: 18-178-15
DATE: 03/02/15

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering than what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2015	BRZ	Engine Mechanical	EM-109-112	Cylinder Block inspection steps changed/updated.
		Door Lock	DL-97	Keyless ID registration steps changed/updated.
2014	BRZ	Summary	IN-12,13	Some Camshaft and valve specifications changed.
		Engine Control	ES-82-89	Diagnostic steps added for DTCs P0000A,000C, 0011,0021.
			ES-375	Diagnostic steps changed/updated for DTCs P0851, 852.
		Engine Mechanical	EM-35,49,50,56,80,82,84	Camshaft and valve inspection and specifications changed/updated.
			EM-109-112	Cylinder Block inspection steps changed/updated.
		Fuel	FU-77-80	Fuel Filler Pipe exploded view, removal, installation and inspection has been added.
		Automatic Transmission	AT-263	No. 4 brake clutch pack clearance adjustment changed.
AT-308	Vent tube installation steps changed.			
Door Lock	DL-97	Keyless ID registration steps changed/updated.		

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2013	BRZ	Engine Control	ES-82-89	Diagnostic steps added for DTCs P0000A,000C, 0011,0021.
			ES-377	Diagnostic steps changed/updated for DTCs P0851, 852.
		Engine Mechanical	EM-109-112	Cylinder Block inspection steps changed/updated.
		Fuel	FU-74-77	Fuel Filler Pipe exploded view, removal, installation and inspection has been added.
		Automatic Transmission	AT-261	No. 4 brake clutch pack clearance adjustment changed.
			AT-303	Vent tube installation steps changed.
		Door Lock	DL-97	Keyless ID registration steps changed/updated.
		Outer Mirror	MX-6	Disassembly steps changed.
2007	B9 Tribeca	Transmission	5AT(diag)-91	Diagnostic steps for DTC P0882 changed/updated.
		Body	LAN(diag)-80	Diagnostic steps for DTC U1321 changed/updated.
2006	B9 Tribeca	Transmission	5AT(diag)-95	Diagnostic steps for DTC P0882 changed/updated.
		Body	LAN(diag)-72-74	Diagnostic steps for DTC U1321 changed/updated.