

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2008MY Forester
2011-2015MY Forester

NUMBER: 18-179-15
DATE: 03/04/15

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering than what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2015	Forester	Engine 1	EN(H4DO)(diag)-94,101	Diaganostic step added at step 1 for DTCs P0011,0021
			EN(H4DO)(diag)-221	Diagnostic steps changed for DTC P0463.
		Engine 2	FU(H4DOTC)-123	Manifold Absolute Pressure Sensor inspection steps changed/updated.
			FU(H4DOTC)-130	Front Oxygen Sensor (A/F) Sensor inspection steps changed.
			EN(H4DOTC)(diag)-96,99,110,113	Diaganostic step added at step 1 for DTCs P0011,0014,0021,0024
			EN(H4DOTC)(diag)-272	Diagnostic steps changed for DTC P0463.
		Transmission	CVT(diag)-57,62,91,94,97,133,137	Diagnostic steps changed for DTCs P0716, 072, 0841, 0842, 0843, 2747, 2751.
		Chassis	BR-21,35	Instructions for disc resurface instead of replacement is added.
			BR-71,72	Stop Light Switch installation and inspections steps changed/updated.
			BR-73,74	Stop Light Switch adjustment steps added.
		Body	AC-89-92,105	Inspection steps changed for the Evaporator Sensor.
			IDI(diag)-33	Diagnostic steps changed for DTC B1500.
			IDI(diag)-37,38	Diagnostics with Phenomenon step is added for MFD display screan.
			BC(diag)-37-40	Diagnostic steps changed for DTC B1500.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2014	Forester	Engine 1	EN(H4DO)(diag)-95,102	Diaganostic step added at step 1 for DTCs P0011,0021
			EN(H4DO)(diag)-218	Diagnostic steps changed for DTC P0463.
			EN(H4DO)(diag)-242	Diagnostic steps changed for DTC P0606.
		Engine 2	FU(H4DOTC)-122	Manifold Absolute Pressure Sensor inspection steps changed/updated.
			FU(H4DOTC)-125	Removal and installation steps changed for Wastegate control valve.
			FU(H4DOTC)-130	Front Oxygen Sensor (A/F) Sensor inspection steps changed.
			FU(H4DOTC)-133	Rear Oxygen Sensor inspection steps changed.
			EN(H4DOTC)(diag)-95,98,109,112	Diaganostic step added at step 1 for DTCs P0011,0014,0021,0024
			EN(H4DOTC)(diag)-268	Diagnostic steps changed for DTC P0463.
			EN(H4DOTC)(diag)-292	Diagnostic steps changed for DTC P0606.
		Transmission	CVT(diag)-57,62,91,94,97,133,137	Diagnostic steps changed for DTCs P0716, 072, 2746, 2750.
		Chassis	BR-21,35	Instructions for disc resurface instead of replacement is added.
			BR-71,72	Stop Light Switch installation and inspections steps changed/updated.
			BR-73,74	Stop Light Switch adjustment steps added.
		Body	ET-7,29-31	Rearview Camera inspection and adjustment notes/cautions changed.
			IDI(diag)-32	Diagnostic steps changed for DTC B1500.
			IDI(diag)-36,37	Diagnostics with Phenomenon step is added for MFD display screen.
BC(diag)-37-40	Diagnostic steps changed for DTC B1500.			
2013	Forester	Engine 1	EN(H4DO)(diag)-94,97	Diaganostic step added at step 1 for DTCs P0011,0021
		Body	AC-89-92,105	Inspection steps changed for the Evaporator Sensor.
2012	Forester	Engine 1	EN(H4DO)(diag)-97,100	Diaganostic step added at step 1 for DTCs P0011,0021
		Body	AC-43-46	Inspection steps changed for the Evaporator Sensor.
2011	Forester	Engine 1	EN(H4DO)(diag)-91,94	Diaganostic step added at step 1 for DTCs P0011,0021
2008	Forester	Transmission	4AT(diag)-53,54	Diagnostic steps changed for DTC P0725.