

INTRODUCTION

This bulletin announces availability of a design change to the power steering pump to address customer concerns of increased steering effort, especially in cold temperatures.

PART INFORMATION

NEW PART NUMBER	DESCRIPTION	APPLICABILITY
34430AJ031	PUMP ASSY	2010-12MY
34430AJ071		2013-14MY

SERVICE PROCEDURE / INFORMATION

If you receive a customer concern of increased steering effort as described above, replace the power steering pump assembly following the procedure in the applicable Service Manual.

WARRANTY / CLAIM INFORMATION

For vehicles within the Basic New Car Limited Warranty period, this repair may be claimed using the following information:

LABOR DESCRIPTION	LABOR	FAIL	LABOR
	OPERATION #	CODE	TIME
Power Steering Pump Assy. R&R	A657-751	RAY21	0.9

Time includes Pressure Checks and System Bleeding.

REMINDER: SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.

• Always refer to STIS for the latest service information before performing any repairs.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotiveproducts in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.