

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2014 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE INFORMATION

APPLICABILITY: 2015MY Forester

NUMBER: 07-92-15

SUBJECT: Condensation (Fogging) in Rear Combination Lamps

DATE: 07/08/15

INTRODUCTION

This **Service Information** bulletin announces a design change to the rear combination lamps to address customer concerns of fogging or condensation accumulating on the inside surface of the lens. Six additional breathing holes have been added to the body of the lamp assembly. The additional holes are intended to provide additional ventilation and prevent fogging which may result when severe ambient temperature changes occur.


NOTE: Fogging is a natural phenomenon and not a defect or malfunction.

COUNTERMEASURE IN PRODUCTION:

The new combination lamps were incorporated into production starting with VIN F*530822.

PART INFORMATION

PART NAME:	PART NUMBER:
LENS & BODY COMPL LH	84912SG041
LENS & BODY COMPL RH	84912SG051



Rear view of the new combination lamp showing the 6 additional breathing holes.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.


Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

SERVICE PROCEDURE / INFORMATION

The service procedure for replacement of the combination lamp is unchanged. Refer to the applicable Service Manual for related cautions, notes, procedures and information.



When applicable, see the Labor Time Guide on Subarunet for claim coding details.

REMINDER: SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.

Always refer to STIS for the latest service information before performing any repairs.