

- ATTENTION:**
 GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2015-2016MY BRZ
 2014-2015MY Forester
 2015MY Impreza and XV Crosstrek
 2013-2015MY Legacy and Outback
 2006-2014MY Tribeca
 2015-2016MY WRX and WRX STI

NUMBER: 18-182-15
DATE: 08/21/15

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering than what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2015	Legacy & Outback	Engine	ME(H4DO)-8,17,77	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Chassis	VDC(diag)-60	Diagnostic steps changed for DTC C1431.
		Body	AB(diag)-59,64,78,79,82,130, 133,196,210,220,250, 260	Diagnostic steps changed for DTC's B1622, 1627, 1643, 1648, B16EA, B16EB, B1824, B1813, B1836, B1901, B1906
			ES-2,7,10,11	Image & working cautions changed.
		ES(diag)-10,12	Working cautions changed.	
2014	Legacy & Outback	Engine	ME(H4DO)-8,18,95	New Chain Cover image, & Front Chain Cover Seal Tool updated.
2013	Legacy & Outback	Engine	ME(H4DO)-8,10,20,90	New Chain Cover image, & Front Chain Cover Seal Tool updated.
2014	Tribeca	Body	LAN(diag)-70-73	Diagnostic steps changed for DTC U1302.
2013	Tribeca	Body	LAN(diag)-71-73	Diagnostic steps changed for DTC U1302.
2012	Tribeca	Body	LAN(diag)-70-73	Diagnostic steps changed for DTC U1302.
2011	Tribeca	Body	LAN(diag)-68-71	Diagnostic steps changed for DTC U1302.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2010	Tribeca	Body	LAN(diag)-70-73	Diagnostic steps changed for DTC U1302.
2009	Tribeca	Body	LAN(diag)-75-77	Diagnostic steps changed for DTC U1302.
2008	Tribeca	Body	LAN(diag)-90-92	Diagnostic steps changed for DTC U1302.
2007	Tribeca	Body	LAN(diag)-73-75	Diagnostic steps changed for DTC U1302.
2006	Tribeca	Body	LAN(diag)-67-70	Diagnostic steps changed for DTC U0302.
2015	Impreza	Engine 1	ME(H4DO(w/o HEV))- 8,10,20,142,148,156	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Body 2	ES-2,7,10-12	Image & working cautions changed.
			ES(diag)-10,12	Working cautions changed.
2015	Forester	Engine 1	ME(H4DO)-9,22,105,111	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Engine 2	ME(H4DOTC)-8,17,91,99	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Chassis	VDC(diag)-61	Diagnostic steps changed for DTC C1431.
2014	Forester	Chassis	VDC(diag)-61	Diagnostic steps changed for DTC C1431.
2016	WRX & STI	Engine 2	ME(w/o STI)-9,90,99	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Chassis	VDC(diag)-82	Diagnostic steps changed for DTC C1431.
		Body	LI-9	HID Headlight system trouble shooting chart added.
			ES-2,8,11-13	Image & working cautions changed.
2015	WRX & STI	Engine 2	ME(w/o STI)-9,18,92,101	New Chain Cover image, & Front Chain Cover Seal Tool updated.
		Chassis	VDC(diag)-64	Diagnostic steps changed for DTC C1431.
		Body	LI-9	HID Headlight system trouble shooting chart added.
2015	BRZ	Preparation Items	SST	Front Chain Cover Seal Tool added.
		Engine Mechanical	Installation	Steps changed