GENERAL MANAGER I PARTS MANAGER I CLAIMS PERSONNEL I SERVICE MANAGER I SERVICE MANAGER I SERVICE MANAGER I SERVICE MANAGER I SERVICE BULLETIN

IMPORTANT - AII

APPLICABILITY: 2015MY Legacy Models

ATTENTION:

SUBJECT: Procedure to Improve Fit and Operation of the Fuel Filler Door (Flap)

NOTE: Service Bulletin 09-58-14 (Procedure to Improve Fit and Operation of the Fuel Filler Door) has been deleted from STIS and has been replaced with Service Bulletin 09-61-15R (Design Change to the Fuel Filler Door Assembly).

If you have copies of 09-58-14 please discard and refer to 09-61-15R for the latest procedure.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotiveproducts in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



QUALITY DRIVEN® SERVICE

NUMBER: 09-58-14R DATE: 09/26/14

REVISED: 12/10/15