



**NOTIFICATION OF UPDATE PRIOR TO SALE
UPSO215-1b: 3.0L V6 CONNECTING ROD
SECURING BOLTS**

**SERVICE
BULLETIN**

13-JAN-15 | NO.: 6-257USA | SECTION: GENERAL INFORMATION | MARKET: USA

DESCRIPTION

A potential issue has been identified on a limited number of 2015 model year XF (X250) vehicles, fitted with the 3.0L SC V6 engine only, where the engine connecting rod securing bolts may not be to the correct torque specification.

AFFECTED VEHICLES

The VINs of affected vehicles are: U60702, U61653, U62555, and U62909.

See the attached list of affected vehicles and retailers.

ACTION TO BE TAKEN

Retailers are required to check DDW to ensure a vehicle is affected by Program Code 'K268' and **HOLD** only *affected* new vehicles in your control and withhold them from onward distribution and sale pending further notice.

Instructions on actions required for affected vehicles already in the hands of customers will be communicated when a repair is finalized.

SERVICE PROGRAM

Jaguar Land Rover is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for these vehicles.

Thank you for your cooperation in this matter. Jaguar Land Rover apologizes for any inconvenience this may cause.

UPSO215-1b: AFFECTED VIN LIST

VIN	RETAILER NO. / NAME	SOLD / RETAILER STOCK [as of 12-JAN-15]
U61653	5320 Jaguar Palm Beach	Sold
U60702	5544 Cherry Hill Classic Cars	Retailer stock
U62909	5544 Cherry Hill Classic Cars	Retailer stock
U62555	5641 Warren Henry Jaguar	Retailer stock