

Reference	SSM72153
Models	F-TYPE / X152 XF / X250 XJ / X351
Title	DVD 139 15 TCM flashing D
Category	Driveability
Last modified	29-Jan-2015 00:00:00
Symptom	614000 Lack/Loss of Power
Attachments	
Content	<p><u>Issue:</u> For the models identified above, a concern has been identified with the latest TCM software released on DVD 139 Patch 15.</p> <p><u>Cause:</u> Currently under investigation with JLR Engineering.</p> <p><u>Action:</u> Please do not use the TCM software for any Transmission / shift related issue's reported by a Customer.</p>