

Reference	SSM72302
Models	F-TYPE / X152 XE / X760 XF / X260 XJ / X351
Title	B1412-96 is being flagged in the Gateway Module
Category	Electrical
Last modified	24-Aug-2015 00:00:00
Symptom	203000 Basic Electrical
Content	<p>Note: This is only applicable to the following vehicles and models years XJ(X351) 13MY onwards F Type(X152) 14MY onwards XE(X760) 16MY onwards. XF(X260) 16MY onwards</p> <p>Issue B1412-96 being flagged in the Gateway Module</p> <p>Cause Under Investigation.</p> <p>Action False log of DTC 1412-96 in the Gateway Module and will not clear due to internal software issues. This will not affect the vehicle performance and is not visible to the customer.</p> <p>If DTC 1412-96 is identified:</p> <ol style="list-style-type: none">1. Do not replaced the Gateway Module for this DTC.2. Do not replace the Quiescent Relay Box for this DTC. <p>SDD will be updated in due course.</p>