
Reference	SSM72498
Models	F-TYPE / X152 XE / X760 XF / X250 XF / X260 XJ / X351
Title	Wheel Stud Overload Failures
Category	Chassis
Last modified	04-Nov-2015 00:00:00
Symptom	306000 Tyres/Wheels

Content

Issue: Wheel stud failures (fractures).

Cause: Overload fracture due to incorrect torque being applied or incorrect process application and sequence being applied to the wheel stud following wheel removal and refit.

Action: Ensure that the correct torque is applied in the correct sequence as detailed in Topix Section 204-04: Wheels and Tires.