
Reference	SSM72202
Models	XF / X250 XK / X150
Title	XF/XK Door Latch functionality
Category	Body
Last modified	17-Dec-2015 00:00:00
Symptom	112000 Latches/Locks & Security
Attachments	111Latch Date Code Example.pdf (111Latch Date Code Example.pdf)

Content

Issue: Door latch functionality

Cause: JLR Engineering are currently investigating side door latch concerns and therefore would appreciate more information to aid investigations.

Action: It is important that the symptom driven diagnostics procedures within TOPIx section 501-14 (lock latches and entry system diagnosis and testing) are adhered to and that no latches are replaced unless this process is followed completely. This will ensure that the root cause of any issue is fully proven and that any unnecessary replacements are prevented.

Upon removal of the door latch please check the date code (Location illustrated in the attachment). If the date code is post 16/03/2015 please submit an EPQR as a parts return maybe required.

