

Reference	SSM72555
Models	XJ / X351
Title	XJ / X351 16MY InControl Touch Pro Navigation Map Update - incorrect website displayed.
Category	Diagnostic Software Hardware
Last modified	17-Dec-2015 00:00:00
Symptom	000101 Diagnostic Concerns
Content	<p><u>Issue:</u> During the Pre-Delivery inspection, the application 'InControl Touch Pro Navigation Map Update' is required to be completed using Symptom Driven Diagnostics (SDD).</p> <p>When the application is launched, the user is presented with an on screen message instructing them to visit a website to download map software. The website displayed on SDD is incorrect.</p> <p>'www.navigation.com/jaguar' = incorrect website</p> <p><u>Action:</u></p> <p>Please review the relevant service bulletins for InControl Touch Pro Map Installation instructions and links to HERE Online dealer order center (DOC). :</p> <ul style="list-style-type: none">• USA : 6-285USA (JBN/Product Support/workshop admin.)• CAN : JLRCS-1511.02 <p>Full details of the InControl Touch Pro Map Installation are available in TOPIx workshop manual 101-01:Pre-Delivery Inspection Manual.</p> <p>The application will be amended to display the correct websites This SSM will be updated when the SDD software level and release date are known.</p>