Reference	SSM72443
Models	XF / X260
Title	K325 UPS 10415-2 AEB BRACKET DEBOND CHECK PROCEDURE VIDEOS
Category	Body
Last modified	05-Oct-2015 00:00:00
Symptom	107000 Interior Trim
Attachments	1BAD.MOV (1BAD.MOV) 1GOOD.MOV (1GOOD.MOV)
Content	

## Issue:

On some X260 Models with AEB, there may be instances of brackets debonding from the glass

## Cause:

Incorrect manufacturing process at the supplier

## Action:

The attached videos are supplementary to the K325 UPS10415 - 2, and show how to check a GOOD verus BAD example of security of the bracket, and should be used as additional supporting information to that service instruction.