

---

<b>Reference</b>	SSM72460
<b>Models</b>	XJ / X351
<b>Title</b>	X351 XJ Front bumper splitter trim coming adrift
<b>Category</b>	Body
<b>Last modified</b>	08-Oct-2015 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories
<b>Attachments</b>	Front splitter adhesive examples.pdf (Front splitter adhesive examples.pdf)

---

**Content**      **Issue:** On some XJ X351 Models, the front lower bumper splitter trim is working loose and / or coming adrift

**Cause:** Under investigation

**Action:** Should you experience this condition, please submit an ePQR with pictures of the nature of the failure, specifically showing a close up and distance shot of the adhesive strip which retains the trim to the bumper assembly. (Please see attached as an example of the close up pictures required)

Additionally, if you are within 100 miles of the Castle Bromwich plant and experience a failure, please contact [dblackh2@jaguarlandover.com](mailto:dblackh2@jaguarlandover.com) to possibly arrange a visit from engineering.

