

October 1, 2015

51807-01909 Version 7

## Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-049, *Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized*

If you did the repair in Service Bulletin 14-023 on or before September 30, 2015 (RO date), use the Warranty Claim Information provided below.

### Replacing the front passenger's airbag inflator

Year/Model	Operation Number	Replacement Part number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003 MDX	7541A9	04785-S3V-306	0.7 hr	5JK00	JK200	14-023N	06780-S3V-A10ZA
	7541A9	04790-S3V-305	0.7 hr	5JK00	JK200	14-023P	06780-S3V-A10ZA

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.