

October 1, 2015

49387-01883 Version 12

Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-067, Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized

If you did the repair in Service Bulletin 13-034 on or before September 30, 2015 (RO date), use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Year/Model	Operation Number	Replacement Part Number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2001–03 Civic 2001–02 Civic GX 2003 Civic Hybrid	7521F7	04785-S5A-307	0.7 hr	5SK00	S9500	13-034A	06780-S5A-A80ZA
	7521F7	04790-S5A-308	0.7 hr	5SK00	S9500	13-034B	06780-S5A-A80ZA
2002–03 CR-V	7521F7	04785-S9A-307	0.7 hr	5SK00	S9500	13-034C	06780-S9A-A80ZA
	7521F7	04790-S9A-308	0.7 hr	5SK00	S9500	13-034D	06780-S9A-A80ZA
2002 Odyssey	7521F7	04785-S0X-307	0.7 hr	5SK00	S9500	13-034E	06780-S0X-A10ZA
	7521F7	04790-S0X-308	0.7 hr	5SK00	S9500	13-034F	06780-S0X-A10ZA

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.