Service Bulletin

## October 23, 2015

02635 Version 1

## Safety Recall: Rear Grab Handle Brackets

## **AFFECTED VEHICLES**

Year	Model	Trim	VIN Range
2015-16	Fit	LX without moonroof	Check the iN VIN status for eligibility

## BACKGROUND

Certain 2015–2016 model year Honda Fit vehicles were equipped with a rear grab rail bracket that was not manufactured to design specifications and may interfere with side curtain airbag deployment. In the event of a collision, if the side curtain airbag does not deploy as designed, the vehicle may fail to comply with the requirements of FMVSS 214, FMVSS 226, and the risk of injury is increased.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.