


<b>Subject:</b>  FRONT SCUFF PLATE COMES OFF TOO EASILY	<b>Bulletin No:</b> 09-035/15
	<b>Last Issued:</b> 09/03/2015

## APPLICABLE MODEL(S)/VINS

2016 MX-5 with VINS lower than JM1ND\*\*\*\*\*101879 (produced before June 11, 2015)

## DESCRIPTION

On some vehicles, the right and/or left side front scuff plate (A) may come off too easily with little force, such as when wiping it with cloth or removing the protective cover on it. The retaining force of the scuff plate clips (B) may be insufficient. To correct the problem, the shape of the scuff plate clips has been changed to increase the retaining force.



Customers having this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the affected side scuff plate(s) with the modified one(s) according to the instructions on MS3 online or the Workshop Manual (section 09-17 SCUFF PLATE REMOVAL/INSTALLATION).
3. Verify repair.

## PART(S) INFORMATION

Part Number	Description	Qty.
N243-68-710A-02	Scuff Plate (RH)	1
N243-68-720A-02	Scuff Plate (LH)	1

## WARRANTY INFORMATION

**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty.
- Additional diagnostic time cannot be claimed for this repair.
- This TSB can be performed by D329 Mazda Certified Lube Technicians.

Warranty Type	A
Symptom Code	91
Damage Code	97
Part Number Main Cause	N243-68-710A02 / N243-68-720A02
Qty.	1
Operation Number / Labor Hours:	XXL5JXRX / 0.2 Hrs.
TSB can be performed by D329 Mazda Certified Lube Technicians:	Yes