

Reference	SSM41438
Models	Range Rover Sport / L320
Title	Stabilizer bar fluid weep - Dynamic Response vehicles.
Category	Chassis
Last modified	05-Jan-2015 00:00:00
Symptom	304000 Suspension System
Attachments	Stabilizer bar pipe o-rings.pdf

ContentIssue:

Misdiagnosis of minor fluid leaks from the stabilizer bar.

Action:

In order to correctly diagnose the leak path on a stabilizer bar, clean the suspected area thoroughly and confirm if the leak is from the pipe o-rings, the stabilizer bar hydraulic seal or somewhere else. If found to be from the pipe o-rings (see attached document), these are serviceable parts and should be replaced.

If the leak is found to be from the hydraulic seal, this is not a serviceable part and a new stabilizer bar will be required.

ARC pipe to Actuator joint

