

Reference	SSM44211
Models	LR3 / L319 Range Rover Sport / L320
Title	Front Suspension Lower Arm Bush Knock.
Category	Chassis
Last modified	05-Jan-2015 00:00:00
Symptom	304000 Suspension System
Attachments	Lower arm front bush.pdf
Content	<p><u>Issue:</u> A review of Front Lower Control Arm warranty returns from various markets has shown that arm assemblies have been incorrectly changed for knock issues when the front bush is cracked and should have been replaced as per Technical Service Bulletins LTB00204v4 and LTB00123v4.</p> <p><u>Cause:</u> Incorrect diagnosis of front and rear bush issues. See attached photo showing an example of a cracked front bush.</p> <p><u>Action:</u> If source of a knock is suspected to be the front lower arm, then thorough inspection of both front and rear bushes is required. Refer to the above mentioned Technical Service Bulletins.</p>

Cracked Front Bush

