

TECHNICAL BULLETIN
LTB00725v2
19 MAR 2014



© Jaguar Land Rover Limited
All rights reserved.

This reissue replaces all previous versions. Please destroy all previous versions. This bulletin supersedes TSB LTB00725/2014 dated 11 DEC 2014, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIX.

Changes are highlighted in gray

SECTION: 206-04

350mm Diameter Rear Brake Squeal During Light Braking - Vehicles With Standard Brakes Only

AFFECTED VEHICLE RANGE:

Range Rover (LG)

Model Year: 2014-2015

VIN: EA124982-FA197898

With: Standard Brakes

Range Rover Sport (LW)

Model Year: 2014

VIN: EA300000-EA399999

With: Standard Brakes

Range Rover Sport (LW)

Model Year: 2014-2015

VIN: EA500000-FA505227

With: Standard Brakes

Range Rover Sport (LW)

Model Year: 2014

VIN: EA600000-EA601437

With: Standard Brakes

MARKETS:

USA and MENA

CONDITION SUMMARY:

Situation: A customer may report a concern of a squeal noise from the rear of the vehicle whilst braking. Usually this will occur at low speeds.

This Version has been issued to add MENA to the Markets.

Cause: The shape of the brake pad means that under certain braking conditions it will resonate causing a squeal noise. **Suggested Customer Concern Code GB5.**

Action: Should a customer express concern, follow the Service Instruction outlined below.

PARTS:



NOTE: The rear brake pad wear sensor does not require replacement if in a satisfactory condition.

LR068303

Rear brake pad kit

Quantity: 1

LR033295


Rear brake pad wear sensor

Quantity: 1

TOOLS:

No Tools Required

WARRANTY:

 **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

 **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Rear brake pad - set - renew	70.40.03	1.1	42	LR036574

 **NOTE:** Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1. Install a new set of rear brake pads (see TOPIx Workshop Manual Section 206-04).