



ABOVE & BEYOND

SERVICE BULLETIN

NOTIFICATION OF UPDATE PRIOR TO SALE
UPS0315-1b: 3.0L V6 CONNECTING ROD SECURING BOLTS

02-FEB-15 | No.: SGI15-01 (issue 2) | SECTION: GENERAL INFORMATION | MARKET: USA

CHANGES ARE HIGHLIGHTED IN GRAY

DESCRIPTION

An issue has been identified on a limited number of 2015 model year LR4 (L319) and Range Rover Sport (L494) vehicles fitted with the 3.0L SC V6 engine where the engine connecting rod securing bolts may not be to the correct torque specification.

AFFECTED VEHICLES

The VIN of each affected vehicle and selling retailer is:

- LR4 (L319) FA745942; Land Rover Buckhead
• Range Rover Sport (L494) FA602430; Land Rover Willow Grove

ACTION TO BE TAKEN

Retailers are required to check DDW to ensure a vehicle is affected by Program Code 'Q448' and HOLD only affected new vehicles in your control and withhold them from onward distribution and sale pending further notice.

Instructions on actions required for affected vehicles already in the hands of customers will be communicated when a repair is finalized.

SERVICE PROGRAM

Land Rover is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for these vehicles.

Thank you for your cooperation in this matter. We apologize for any inconvenience this may cause.