

<b>Reference</b>	SSM72205
<b>Models</b>	Discovery Sport / L550 LR2 / L359 Range Rover / L322 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L320 Range Rover Sport / L494
<b>Title</b>	Fault code F000-63/U3000-63 logged in the KVM(Keyless vehicle module)
<b>Category</b>	Electrical
<b>Last modified</b>	05-Mar-2015 00:00:00
<b>Symptom</b>	203000 Basic Electrical
<b>Content</b>	<p><b><u>Issue</u></b> Only applicable to software versions 30.3 (GEN 3) FK72-14C104-AF and 29.3 (GEN 2) DPLA-14C104-AG When checking for fault codes logged in the KVM (keyless vehicle module) also known as the RFA (remote function actuator) F000-63/U3000-63, Control Module - Circuit/ Component Protection Time-Out is logged.</p> <p><b><u>Cause</u></b> This DTC is set when the KVM has gone through a “self reset”</p> <p><b><u>Action</u></b> This DTC will not have any effect on functionality. The module must not be replaced .Please carryout a DTC clear. There is a possibility that it will keep appearing This issue will be resolved with a later release of software.</p>