TECHNICAL BULLETIN LTB00703NAS1 21 JUL 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 413-00

Intermittent Display Of Audio Track Information On The Instrument Cluster

<u>AFFECTED VEHICLE RANGE:</u>

Range Rover Sport (LW)Model Year:2014VIN:000001-504510Manufacturing Plant:Solihull

Range Rover (LG)Model Year:2014VIN:124982-197041Manufacturing Plant:Solihull

<u>MARKETS:</u>

NAS

CONDITION SUMMARY:

Situation: The audio track information may intermittently not be displayed in the Instrument Cluster at the start of CD, USB, or iPod® playback.

Cause: This may be caused by the Instrument Cluster not interpreting certain strings of characters in the track title.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

No Parts Required

<u> TOOLS:</u>

NOTE: this is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.

SDD with latest DVD and Calibration File

Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

ONOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.