

Reference	SSM72284
Models	Range Rover / L405 Range Rover Sport / L494
Title	2015 Touch Screen Display Resets While Driving
Category	Electrical
Last modified	31-Jul-2015 00:00:00
Symptom	207000 Entertainment Systems
Content	<u>PLEASE NOTE THE ISSUE DETAILED IN THIS SSM HAS NOW BEEN RESOLVED, PLEASE REFER TO TSB LTB00811NAS1 POSTED TO TOPIX FOR INSTRUCTIONS ON UPDATING FCDIM (TOUCH SCREEN) SOFTWARE TO REMEDY THIS CONCERN.</u>

Models affected

15MY Range Rover / L405
15MY Range Rover Sport / L494

Issue

A customer may experience their Touch Screen resetting / going "black/blank" during their ignition cycle and then restarting as if the ignition was cycled. The Land Rover logo will appear and the system will function normally after the reset occurs.

Cause

Touch Screen software concern.

Action

Do not attempt to program or replace the Touch Screen for this issue. A new software is being developed and a further communication will be issued in due course.