Reference	SSM72324
Models	Discovery Sport / L550
	Range Rover Evoque / L538
Title	Trim finishers and body damaged/marked
Category	Body
Last modified	01-Jul-2015 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	damage.pdf
Content	Issue:
	Now vahiolog arriving at Ports or Potailors are being reported to have damage but without sufficient information to understand the

New vehicles arriving at Ports or Retailers are being reported to have damage but without sufficient information to understand the concern.

#### Cause:

More information is required to better understand the issue to support investigation and rectification.

# Action:

Inspect vehicle protective covers - film or body cover, for potential damage to the parts underneath. Example: cracks should appear as creases through the white protective film as seen in the attached file.

Please report any damage through an EPQR and add photo's of both the protection damage and the part.

# Associated areas can be:

### External -

- A pillar
- B pillar
- C pillar
- D pillar

#### Internal -

- Driver's door pad
- Centre console
- Centre console side finishers (L550 Discovery Sport only)
- Driver's seat bag
- Plastic sticky cover to carpets
- Steering wheel

