| Reference     | SSM72325  |
|---------------|---|
| Models        | Discovery Sport / L550  |
|               | Range Rover / L405  |
|               | Range Rover Evoque / L538   |
|               | Range Rover Sport / L494  |
|               | · · · · · · · · · · · · · · · · · · ·   |
| Title         | DTC U001187 Medium Speed CAN BUS performance - Missing Message  |
| Category      | Electrical  |
| outogo. y     | <u> </u>  |
| Last modified | 14-Jul-2015 00:00:00  |
|               |   |
| Symptom       | 205000 Electrical Accessories   |
|               |   |
| Content       | <b>Issue:</b> Diagnostic Trouble Code (DTC) U001187 'Medium Speed Can Communication Bus Performance – Missing Message' may be noted in the Auxiliary Control Module (AUCM) during a Symptom Driven Diagnostics (SDD) fault code read. |
|               | Cause: Software calculation.  |
|               | <b>Action:</b> If the DTC U001187 is present in the AUCM and the customer has reported a concern with the Head Up Display (HUD) functionality, then continue with diagnostics using SDD and with reference to TOPIx.                  |
|               | If the customer has not reported an issue with the HUD system, then the DTC can be dis-regarded and no further investigation into its origin required.  |
|               |   |