Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2015 Mazda Motor of America, Inc.

Subject: Bulletin No: 09-046/15

WHITE DOOR ARMREST(S) PINK DISCOLORATION


Last Issued: 12/22/2015

APPLICABLE MODEL(S)/VINS

2014-2016 Mazda6 vehicles with VINs lower than JM1 GJ ***** 458701 (produced before November 09, 2015)

DESCRIPTION

Some customers may complain about a white door armrest(s) pink discoloration. The discolored armrest does not match the other white parts of the door panel.



Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

- 1. Verify customer concern.
- 2. Replace all 4 door panels. Refer to MS3 online or Workshop Manual section 09-17:
 - FRONT DOOR TRIM REMOVAL/INSTALLATION
 - REAR DOOR TRIM REMOVAL/INSTALLATION
- 3. Verify repair.

Bulletin No: 09-046/15	Last Issued: 12/22/2015
© 2015 Mazda Motor of America, Inc.	

PART(S) INFORMATION

Part Number	Description	Qty.	Note
GMN5-68-420D-39 *	TRIM(R),DOOR	1	
GMN5-68-450D-39 *	TRIM(L),DOOR	1	
GMN6-68-420D-39 *	TRIM(R),DOOR	1	Replace all 4
GMN6-68-450D-39 *	TRIM(L),DOOR	1	door panels
GMN5-68-520B-39 *	TRIM(R),DOOR-REAR	1	
GMN5-68-550B-39 *	TRIM(L),DOOR-REAR	1	

^{*} Use GEPC with VIN to lookup part number.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- This TSB can be performed by D329 Mazda Certified Lube Technicians.
- · Additional diagnostic time cannot be claimed for this repair.
- · Replace all 4 door panels.

Warranty Type	А
Symptom Code	49
Damage Code	9X
Part Number Main Cause	**** 68 420, ****68 450, ****68 520, ****68 550
Quantity	1
Operation Number / Labor Hours:	XXL97XRX / 0.6 Hrs.
TSB can be performed by D329 Maz- da Certified Lube Technicians:	Yes