
Reference	SSM72294
Models	Range Rover / L405
Title	Range Rover (L405) front door check strap noise
Category	Body
Last modified	24-Aug-2015 00:00:00
Symptom	111000 Body Panel(s)/Unibody

Content Issue: Noise from the front door check strap on Range Rover (L405) - part number LR045540.

Cause: On some vehicles the front door check strap fixing bolts torque may be too low.

Action: Improvements were made in the assembly process for the bolt torques. The assured VIN for Range Rover (L405) is 206763. ePQR are not required to report these issues on vehicles before the assured VIN. Repair the issue as required - TOPIX section 501-03. (10.5Nm)