
Reference	SSM72384
Models	Range Rover Evoque / L538
Title	Noise from heater/ air-conditioning blower motor
Category	Electrical
Last modified	24-Aug-2015 00:00:00
Symptom	208000 Climate Control

Content**Issue**

Complaints of noise from heater/ air-conditioning blower motor.

Cause

Engineering investigations have found that the noise may possibly in some circumstances, be caused by loose objects or material within the blower motor housing.

Action

If a vehicle is brought in to the dealership with the above complaint:

- Confirm if there are any loose objects or parts inside the housing.
- Submit an EPQR
- Provide photo's of the objects / parts found to be loose.
- Retain for potential return to Engineering.