

---

<b>Reference</b>	SSM72387
<b>Models</b>	Discovery Sport / L550 LR4 / L319 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
<b>Title</b>	Transportation Steering Wheel Cover Not Fitted
<b>Category</b>	Body
<b>Last modified</b>	24-Aug-2015 00:00:00
<b>Symptom</b>	107000 Interior Trim
<b>Content</b>	<p><b><u>Issue:</u></b> Residue being left on steering wheel when transportation steering wheel cover is removed.</p> <p><b><u>Cause:</u></b> Under investigation.</p> <p><b><u>Action:</u></b> Until further notice all Land Rover &amp; Range Rover vehicles will be supplied without the transportation steering wheel cover fitted.</p>