

<b>Reference</b>	SSM72399
<b>Models</b>	Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
<b>Title</b>	Power Steering Control Module DTC 0x000000
<b>Category</b>	Chassis
<b>Last modified</b>	31-Aug-2015 00:00:00
<b>Symptom</b>	303000 Steering/Handling

**Content**      **Issue:**  
During vehicle diagnostic/servicing check-up the following DTC may be reported for the Power Steering Control Module (PSCM):

*'0000-00 – [No information available]*

There is no customer reportable symptom related to this DTC.

**Cause:**

This DTC has been incorrectly set to be visible in production software.

**Action:**

1. Clear DTC
2. Take no further action based on this DTC.

**Please note:** This **only** applies to DTC 0000-00 and the following vehicle years:

Range Rover (L405) 2016MY  
Range Rover Sport (L494) 2016MY  
Discovery Sport (L550) 2015MY  
Discovery Sport (L550) 2016MY  
Evoque (L538) 2016MY