

<b>Reference</b>	SSM72338
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Park Assist Module Programming
<b>Category</b>	Electrical
<b>Last modified</b>	10-Sep-2015 00:00:00
<b>Symptom</b>	206000 Warning Indicators
<b>Content</b>	<p><u>Models Affected:</u> 15MY Range Rover / L405 15MY Range Rover Sport / L494</p> <p><u>Issue:</u> Customer may report concerns with Automatic Parallel Parking maneuver.</p> <p><u>Cause:</u> Park Assist Module (PAM) software concern.</p> <p><u>Action:</u> With DVD 143.00 and Calibration file 216 loaded on to SDD, program the PAM as existing. After programming is complete select the Service Functions tab and run "Special Applications - Parking aid control module reset". If this procedure is not run after programming, no sound will be heard from the Park Aid Sensors.</p>