

Reference	SSM72418
Models	Discovery Sport / L550
Title	L550 PDI Applicaton Reports Incorrect KVM Software (Updated)
Category	Diagnostic Software Hardware
Last modified	29-Sep-2015 00:00:00
Symptom	000101 Diagnostic Concerns

Content

Issue:

When attempting to complete the Pre Delivery Inspection (PDI) application using Symptom Driven Diagnostics (SDD), you may be instructed that the Keyless Vehicle Module (KVM) software is not at the correct software level and requires updating.

If existing module programming is then attempted you may then prompted that the software loaded to the module is later than SDD is proposing to load and to contact retailer technical support.

Cause:

During the PDI application, SDD is incorrectly checking the KVM software level.

Action:

This concern has now been corrected on SDD 143.02 which was released on 28th September 2015.