

<b>Reference</b>	SSM72424
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Auto High Beam Option Unavailable 16MY only
<b>Category</b>	Electrical
<b>Last modified</b>	10-Sep-2015 00:00:00
<b>Symptom</b>	201000 Lighting Systems
<b>Content</b>	<p><b>Issue:</b> Auto High Beam setting option unavailable in Instrument Cluster menu. Affects the following vehicles only:</p> <p>Range Rover Sport 16MY fitted with Thin Film Transistor (TFT) Instrument Cluster without 'Lane Departure Warning' and 'Traffic Sign Recognition' options fitted.</p> <p>Range Rover 16MY fitted with TFT Instrument Cluster without 'Lane Departure Warning' and 'Traffic Sign Recognition' options fitted.</p> <p><b>Cause:</b> Currently under analysis.</p> <p><b>Action:</b> Land Rover will release a Technical Service Bulletin in the near future stating the necessary service repair procedure. In the meantime, please do not carry out any diagnosis or component replacement to address the concern.</p>