

TECHNICAL BULLETIN

LTB00826NAS1

01 OCT 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-10

'Click' Noise From The Front Left Seat Outer Valance Trim

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)**Model Year:** 2015**VIN:** 501001-532978**Manufacturing Plant:** Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A 'click' noise may be heard when fully moving the front left seat rearwards.**Cause:** This may be caused by a redundant clip moulded into valance catching on seat frame.**Action:** Should a customer express this concern, follow the Service Instruction below.

PARTS:

LR078015	Valance Seat Cushion, left, electric front seat adjustment, non-memory, glacier, driver/passenger electric front seat adjustment/memory	Quantity: 1
LR078016	Valance Seat Cushion, left, electric front seat adjustment non-memory, cirrus, driver/passenger electric front seat adjustment/memory	Quantity: 1
LR078017	Valance Seat Cushion left, electric front seat adjustment non-memory, ivory, driver/passenger electric front seat adjustment/memory	Quantity: 1
LR078018	Valance Seat Cushion left, electric front seat adjustment non-memory, ebony black/ebony black interior, tan, ebony/pimento red, driver/passenger electric front seat adjustment/memory	Quantity: 1
LR078019	Valance Seat Cushion left, electric front seat adjustment, non-memory, almond, driver/passenger electric front seat adjustment/memory	Quantity: 1

TOOLS:

Refer to Workshop Manual for any required special tools.

SECTION: 501-10

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Switch - Front seat control - Glacier - Renew	78.70.89	0.7	41	LR078015
Switch - Front seat control - Cirrus - Renew	78.70.89	0.7	41	LR078016
Switch - Front seat control - Ivory - Renew	78.70.89	0.7	41	LR078017
Switch - Front seat control - Ebony black/ebony black interior, Tan, Ebony/pimento red - Renew	78.70.89	0.7	41	LR078018
Switch - Front seat control - Almond - Renew	78.70.89	0.7	41	LR078019

 **NOTE: Normal Warranty procedures apply.**

SERVICE INSTRUCTION:

- 1 Renew the front left seat outer valance trim (see TOPIx Workshop Manual, section 501-10: Front seat control switch).