

TECHNICAL BULLETIN
LTB00837NAS1
12 NOV 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 307-01

Transmission Cover Gasket Leak

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)

Model Year: 2014 Onwards
VIN: 856580 Onwards
Manufacturing Plant: Halewood

Transmission: 9HP48 9-Speed Automatic
Transmission - AWD

Discovery Sport (LC)

Model Year: 2015 Onwards
VIN: 500116 Onwards
Manufacturing Plant: Halewood

Transmission: 9HP48 9-Speed Automatic
Transmission - AWD

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A fluid leak from the transmission, poor shift quality, and/or transmission noise may be evident.

Cause: This may be caused by the transmission cover gasket having been damaged during manufacture, allowing transmission fluid to leak.

Action: Should a customer express this concern, follow the Service Instruction below.

PARTS:

LR081666	ZF Transmission cover gasket kit	Quantity: 1
LR023288	ATF Transmission fluid	Quantity: 1

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Transmission cover gasket - Renew	44.20.28	0.7	42	LR072666

NOTE: Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1 Install a new transmission cover gasket (see TOPIx Workshop Manual section 307-01: Automatic Transmission/Transaxle - Transmission Cover).