

TECHNICAL BULLETIN
Q511NAS2
23 NOV 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

Changes are highlighted in gray

SECTION: 303-00

Service Action: GTDi Pre-ignition

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)

Model Year: 2012-2014
VIN: 600018-955848
Manufacturing Plant: Halewood

Range Rover Evoque (LV)

Model Year: 2015
VIN: 932947-996114
Manufacturing Plant: Halewood

Range Rover Evoque (LV)

Model Year: 2015
VIN: 000051-065597
Manufacturing Plant: Halewood

LR2 (LF)

Model Year: 2013-2015
VIN: 321215-433283
Manufacturing Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

This program is reinstated with immediate effect.

Situation: An issue has been identified on 2013-2015 model year LR2 (L359) and 2012-2015 model year Range Rover Evoque (L538) vehicles which may experience reduced power or perception of a misfire and difficulty restarting the engine.

Action: Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS: